

การศึกษาสภาวะสิ่งแวดล้อมอาคารที่พักอาศัยในเขตเทศบาลเมืองหาดใหญ่  
เพื่อวางแผนกำกับดูแลศึกษาสำรวจการบังคับอัคคีภัย

ธรรมศาสตร์ ณ เชียงใหม่ \*

บทคัดย่อ

สภาพที่ไม่ช่องเทศบาลเมืองหาดใหญ่ มีพื้นที่ 21 ตารางกิโลเมตร ครอบคลุมพื้นที่  
ที่ก่ำลหากาดใหญ่ห้องหมกและพื้นที่บางส่วนของคำบลอดอนห์ คำบลคนังลัง และคำบลคลองเหน การ  
สำรวจสภาวะสิ่งแวดล้อมของอาคารที่พักอาศัย รวมทั้งสถานประกอบการค้า ฯ โดยใช้แบบสอบถาม  
ถาม การล้มภาษณ์และการสังเกต บริเวณที่เป็นเชิงชุมชนทางแนวโน้มทาง เมืองและย่านธุรกิจ เท่า  
นั้น ได้สำรวจอาคารค้า ฯ รวมทั้งสิ้น 3,810 หลัง แยก เป็นอาคาร ไม้หั้งหลังจำนวน 615 หลัง  
และหน่วยเป็นอาคาร ไม้หั้ม อายุการใช้งานมากกว่า 20 ปี มากถึง 859 หลัง ส่วนใหญ่อยู่บนถนน  
แสงจันทร์ เป็นอาคาร ไม้ 1 ชั้นและ 2 ชั้น ถนนแสงจันทร์ เป็นอาคาร ไม้ 2 ชั้น หลังคลอกกิมหยง  
เป็นอาคาร ไม้ 2 ชั้น ถนนประชาธิรักษ์ บริเวณธนาคารกรุงเทพ จำกัด เป็นอาคาร ไม้ 2 ชั้นและ  
ถนนนิพัทธ์อุทิศ 3 บริเวณร้านช้าวัฒน์ โภชนา เป็นอาคาร ไม้ 2 ชั้น แนวคิดในการกำหนดแผนยุทธ์-  
ศาสตร์ในการปฏิบัติการบังคับอัคคีภัย ควรแบ่งออกเป็น 3 ระดับคือ ก่อนเกิดเหตุ ให้ ชุมชน เกิด  
เหตุ ให้ ชุมชน เกิดเหตุ ให้ผู้สูงอายุทำการ นอกจากนี้ จัดตั้งหมายการรับรู้ มาสัมสนุ์แผน  
คั่งกล่าว ได้แก่ การเพิ่มรากน้ำกระเช้าที่สามารถดับเพลิงสูงกว่า 23 เมตร เพิ่มท่อประปาดับ  
เพลิง และล้อถูกน้ำเพื่อป้องกันไฟไหม้ ให้เพียงพอตามขนาดสถาปัตย์ ที่ได้ระบุว่า เป็นจุดสำคัญที่อาจจะเกิด  
อัคคีภัย หากทางพื้นที่อาคาร ไม้หั้ม จะเป็นสาเหตุของเพลิง ให้ ชุมชน จัดตั้งห้องซ้อมเพลิง ให้  
ความรู้ความเข้าใจ การฝึกอบรมและการฝึกซ้อมการบังคับอัคคีภัยแก่นิวยงาน ทั้ง  
ราชการ เอกชน และประชาชนในเขตเทศบาลอย่างทั่วถึง

\* M.S.E.H., Associate Professor

ภาควิชาเวชศาสตร์ชุมชน คณะแพทยศาสตร์ชุมชน

มหาวิทยาลัยสงขลานครินทร์

A STUDY ON HOUSING ENVIRONMENT IN HATYAI MUNICIPALITY  
FOR FIRE PROTECTION STRATEGIC PLANNING

Narong Na Chiangmai \*

**ABSTRACT**

Hat Yai Municipality has an average area of 21 square kilometres, covering the area of whole Tombon HatYai, parts of Tombon Khor-Hong, Kuan-Lung and Khlong-Hae. Study, focussing particularly in the heart of HatYai town and concentrate business area, was performed by distribution of questionnaire, interview and field observation. 3,810 housings were studied, comprising 915 wooden units, 1,238 concrete and 959 wooden-cum-concreted units. 595 wooden units were found to be over 20 years old, being 1 or 2 story mostly located at Saeng-Chan Road, 2-story wooden unit at Saeng-Athit Road and 2-story wooden unnts of Prachathipat Road adjacent to Bangkok Bang Co., Ltd. and 2 story wooden unit near Ko-Yao food mart. It is recommended that the strategy in preventing fire hazard be categorized into three steps i.e. prior, during and subsequent to the fire breakout. The rescue operation needs to be under a head quater supervised by the Major. Additionally, measure must be supplemented for instance, the procurement of vehicles that can combat fire over 23 metres in height, increase in the fire hydrants for fire extinguishment and warning signal in the area where

the risk of fire breakout is great, improvement of wooden housing which may cause fire and lastly, to create an understanding by educating, training and practice in fire prevention and extinguishment for residents, private and government agencies

---

\* M.S.E.H., Associate Professor

Department of Community Medicine

Faculty of Medicine

Prince of Songkla University