


APPENDIX C
PHOTO COLLECTION OF ENERGY AUDITING



1 Arrival of ribbed unsmoked sheets



2 Rubber washing machine




3 Hanging for drip dry



4 Grading smoked rubber




5 Bale of smoked rubber being coated with talc




6 Installation of thermocouple
on the wall




7 Installation of thermocouple on ceiling



8 Furnace intake hood for inlet air measurement



9 Environmentally controlled chamber



10 Heat pump air drier